




Factory gate



Factory name



Production building




Evacuation plan



Exit sign and emergency light



Fire facilities



Test for emergency light



Test for fire alarm



Test for fire hydrant



Cutting process



Metal working process



Assembly process



Packing process



Finished goods warehouse



amfori BSCI Code



Attendance recorder



Eye washing facility



First aid kit



Potable water




PPE




Suggestion box



Warning signs



NC5.5 Social insurance did not cover all workers



NC6.2 Monthly OT exceeded 36 hours



NC7.1 The factory's partial goods in warehouse were directly leaned against the wall



NC7.13 The outer protection covers of 20% distribution boxes were not locked



NC7.17 40% punching machines' pedals missed protective covers



NC7.17 All riveting machines' pulley protection covers were incomplete



NC7.17 One crane's hook missed safety buckle



NC7.22 Toilets at workshop missed private door

----- END -----